

1) Please confirm which document this representation relates to.

Schedule of Proposed Main Modifications

6) Please use this box for any other comments you wish to make.

The development at Downingbury Farm should enter/exit via Maidstone Road, rather than via Church Road which already has problems with parking and traffic blocking the Maidstone Road by the school. It is particularly dangerous for school children crossing Church Road and Maidstone Road between during school drop off & pick up times. If the development was accessed via the Maidstone Road, were the current entrance to the Farm Shop and houses are it would result in most of traffic from the development exiting directly on to the A228 rather than causing more blockages and hazards outside the school and extra traffic in the village.